




# OCEANREEF®

underwater, naturally.


## Full Face Mask Size Recommendation Chart



\* Faded areas represent less common face measurements. It is very likely that a mask will still fit comfortably even if measurements are located in fading areas.



## Full Face Mask Measuring Directions



1. Adjust caliper length by moving the right slide in the opposite direction from the base
2. Take the Length measurement:
  - a. Adjust caliper so that Point A lies exactly on the bridge of the nose and Point B touches snugly underneath the tip of the chin
  - b. Remove the caliper and record the length measurement
3. Take the Width measurement:
  - a. Rest the inside edge of the caliper on the middle of the nose. Adjust the caliper so that Point A touches the outer edge of the divers left cheek bone and Point B touches the outer edge of the divers right cheek bone
  - b. Remove the caliper and record the width measurement
4. Refer to the Full Face Mask Size Recommendation.
  - a. Locate the length measurement on the y-axis. Then locate the width measurement on the x-axis
  - b. Trace the length measurement to the right, inside of the chart. Trace the width measurement up, inside the chart. Make a note of the location on the chart where the two measurements intersect
  - c. This intersection point will fall into a size category (Small/Medium; Medium/Large; or Both. Both means that the diver may wear either mask; the Small/Medium or Medium/Large)

**\*IF YOU HAVE QUESTIONS, CALL 1-800-922-1764**

